



Parts & Service
Mon - Fri 7AM- 10PM



P:419-729-7010 - P:800-283-9922 - F: 419-729-7019
5015 Enterprise Blvd. Toledo, OH 43612

Expires July 31, 2017 pricing and availability subject to change



Holland FW35

Rebuild Kit - Standard Left Hand Release

Holland FW35 kits # RK-FWS-A-L \$ **199.99**

Having issues with your abs Modulator?

Wish you could know what's wrong by using your cell phone? Replace a S446-108-2010 with a smart one

GEN2-2010 from Dayton Parts \$ **369.57**

Replace a S400-850-6010 w/ a GEN2-6010 \$ **374.89**



- 13.5k capacity
- 17.5 inch wide
- 4" less space than comparable lift axles
- LSZ1313AAMD-AA

\$ **5300.00** SAF Holland Neway




Congratulations Stemco on the new Brakes shoe manufacturing plant in USA!

Do YOU want to see it? This fall we will be arranging a trip!! Till fall Buy new shoes kits, long life slack adjustors, brake chambers and SAVE \$\$\$\$ ask your sales person!

Over 700 parts and 500 service locations



Where ever the road takes you...we are there!



34 CONMET Hubs in stock, starting at \$ 129.00 Save time and Money with Pre Set Hubs!



Freightliner CAC
FRT18106-NV **\$ 400**

replaces

FRT18106,FRT18106N,BTC1105B,B
T1105B,1105B,CAC105B,WSR1105
B,SCSI222032,CA2032
222032,FRDAC2C,DURFRDAC2C,D
HTFR2C,DHT2C,37412C,SRMFR2C,
44FR2C,FL2C,FL2CMA
X
FL2CUS,SPI44011705,44011705,SC
SI1107U,441107,FLX010224,17V9
729,23705,FRCAC002
ABPN09BH2C,S19888,85103364,0
123132000,0123132001,0123547
000,4856120001
4856125001,4863900001,486390
5001,7092730001



Cat 3406B & 3406C water pump
1 year part & Labor
US2035 **\$ 238.55**




AFF 7685 1" 6" anvil
\$ 340.00




Peterbilt hood clamp
Many others in stock
HLK1004 **\$ 8.09**



Delco 8200433 **\$ 250.00**
39MT 12V 12 teeth drive



G2299580300 Holland Neway
airspring replaces 8434, 1R13-118
and 9580 **\$ 116.00**



Actual color Yellow
Cam buckle strap 2" x 12'
Series E or A spring fitting
3000 LBS breaking strenght
1000 lbs working load limit
6126-12 **\$ 6.50** Limit 20



9007 bulb **\$ 2.25**



Torca L50SA **\$ 6.27**



Turbo clamp VT10475
\$ 12.53